

CERTIFICATE OF COMPLIANCE

Certificate Number UL-US-L252760-12-41301102-2
Report Reference E252760-20110314
Date 4-Dec-2021

Issued to: LEROY SOMER
669 NATCHEZ TRACE DR LEXINGTON, TN
United States 38351-4125

This is to certify that JZGZ - Generators
representative samples of See Addendum Page for Product Designation(s).

Have been investigated by UL in accordance with the
Standard(s) indicated on this Certificate.

Standard(s) for Safety: UL 1004-9, 1st Ed., Issue Date: 2016-01-29, Revision Date:
2018-02-02, UL 1004-4, 3rd Ed., Issue Date: 2018-07-02,
UL 1004-1, 2nd Ed., Issue Date: 2012-09-19, Revision
Date: 2020-11-05

Additional Information: See the UL Online Certifications Directory at
<https://iq.ulprospector.com> for additional information

This Certificate of Compliance does not provide authorization to apply the UL Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number UL-US-L252760-12-41301102-2
 Report Reference E252760-20110314
 Date 4-Dec-2021

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements

Model	Category Description
1500kW/4p/208V , 144x-xxx	Polyphase Motor
2130kW/6p/600V , 17xx, Xxx6P6/x-xxxx or Xxx66x-xx	Polyphase Motor
187x	Polyphase Motor
4P8-1, 182x, 184x, xxx4P8.x-xxxx or xxx84xVSxx	Polyphase Motor
4P8-2, 182x, 184x, xxx4P8.x-xxxx or xxx84xSxx	Polyphase Motor
4P8-3, 182x, 184x, xxx4P8.x-xxxx or xxx84xMxx	Polyphase Motor
4P8-4, 182x, 184x, xxx4P8.x-xxxx or xxx84xLxx	Polyphase Motor
4P8-5, 182x, 184x, xxx4P8.x-xxxx or xxx84xVLxx	Polyphase Motor
4P8-6	Polyphase Motor
KH00390Txxx	Polyphase Motor
KH00590Txxx	Polyphase Motor
KH00591Txxx	Polyphase Motor
KH00601Txxx	Polyphase Motor
KH00602Txxx	Polyphase Motor
KH00682Txxx	Polyphase Motor
KH00720Txxx	Polyphase Motor
KH00721Txxx	Polyphase Motor
KH00750Txxx	Polyphase Motor
KH00751Txxx	Polyphase Motor
KH00752Txxx	Polyphase Motor
KH00753Txxx	Polyphase Motor
KH00810Txxx	Polyphase Motor
KH00811Txxx	Polyphase Motor
KH00900Txxx	Polyphase Motor
KH00910Txxx	Polyphase Motor
KH00911Txxx	Polyphase Motor
KH01050Txxx	Polyphase Motor
KH01051Txxx	Polyphase Motor
KH01052Txxx	Polyphase Motor
KH01100Txx	Polyphase Motor
KH01130Txxx	Polyphase Motor
KH01131Txxx	Polyphase Motor
KH01132Txxx	Polyphase Motor
KH01190Txxx	Polyphase Motor
KH01220Txxx	Polyphase Motor
KH01310Txxx	Polyphase Motor
KH01341Txxx	Polyphase Motor
KH01370Txxx	Polyphase Motor
KH01420Txxx	Polyphase Motor

B. Mahlen

Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number UL-US-L252760-12-41301102-2
 Report Reference E252760-20110314
 Date 4-Dec-2021

KH01421Txxx	Polyphase Motor
KH01512Txxx	Polyphase Motor
KH01600Txxx	Polyphase Motor
KH01640Txxx	Polyphase Motor
KH01641Txxx	Polyphase Motor
KH01741Txxx	Polyphase Motor
KH01800Txxx	Polyphase Motor
KH02070Txxx	Polyphase Motor
KH02100Txxx	Polyphase Motor
KH02101Txxx	Polyphase Motor
KH02260Txxx	Polyphase Motor
KH02400Txxx	Polyphase Motor
KH02401Txxx	Polyphase Motor
KH02450Txxx	Polyphase Motor
KH02460Txxx	Polyphase Motor
KH02610Txxx	Polyphase Motor
KH02850Txxx	Polyphase Motor
KH02880Txxx	Polyphase Motor
KH02971Txxx	Polyphase Motor
KH03000Txxx	Polyphase Motor
KH03001Txxx	Polyphase Motor
KH03002Txxx	Polyphase Motor
KH03003Txxx	Polyphase Motor
KH03541Txxx	Polyphase Motor
KH03542Txxx	Polyphase Motor
KH03600Txxx	Polyphase Motor
KH03601Txxx	Polyphase Motor
KH03602Txxx	Polyphase Motor
KH03603Txxx	Polyphase Motor
KH03890Txxx	Polyphase Motor
KH04450Txxx	Polyphase Motor
KH05090Txxx	Polyphase Motor
M2732L4	Polyphase Motor
M2734L4	Polyphase Motor
M2736L4	Polyphase Motor
M2738L4	Polyphase Motor
M2754L4	Polyphase Motor
M2756L4	Polyphase Motor
M2774L4	Polyphase Motor
3ph, M2776L4	Polyphase Motor
M3115L4	Polyphase Motor
3ph, M3134L4	Polyphase Motor
phase 3, M3136L4	Polyphase Motor
M3154L4	Polyphase Motor
M3156L4	Polyphase Motor

B. Mahlen

Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number UL-US-L252760-12-41301102-2
Report Reference E252760-20110314
Date 4-Dec-2021

M3175L4	Polyphase Motor
TAL x42 E, KH00602Txxx, M1736L4, FGL20050 - (3ph)	Polyphase Motor
TAL x42 F, M1754L4, FGL20060 - (3ph)	Polyphase Motor
TAL x42 G, KH00721Txxx, M1756L4, FGL20070 - (3ph)	Polyphase Motor
TAL x42 H, KH00811Txxx, M1775L4, FGL20080 - (3ph)	Polyphase Motor
TAL x44 A, KH00591Txxx, FGL30010 - (3ph)	Polyphase Motor
TAL x44 B, KH00590Txxx, M2233L4, FGL30020 - (3ph)	Polyphase Motor
TAL x44 C, KH00752Txxx, M2235L4, FGL30030 - (3ph)	Polyphase Motor
TAL x44 D, KH00753Txxx, M2236L4, FGL30040 - (3ph)	Polyphase Motor
TAL x44 E, KH01051Txxx, FGL30050 - (3ph)	Polyphase Motor
TAL x44 H, KH01052Txxx, M2254L4, FGL30080 - (3ph)	Polyphase Motor
TAL x44 J, KH01191Txxx, M2256L4, FGL30100 - (3ph)	Polyphase Motor
TAL x44 K, KH01340Txxx, M2275L4, FGL30110 - (3ph)	Polyphase Motor
TAL x44 L, KH01680Txxx, M2294L4, FGL30120 - (3ph)	Polyphase Motor
TAL x44 M, KH01681Txxx, FGL30130 - (3ph)	Polyphase Motor
TAL x46 A, M2732L4 - (3ph)	Polyphase Motor
TAL x46 B, M2734L4 - (3ph)	Polyphase Motor
TAL x46 C, KH01221Txxx, M2736L4, FGL50030 - (3ph)	Polyphase Motor
TAL x46 D, KH01222Txx, M2738L4, FGL50040 - (3ph)	Polyphase Motor
TAL x46 E, KH01642Txxx, M2754L4, FGL50050 - (3ph)	Polyphase Motor
TAL x46 F, KH01643Txxx, M2756L4, FGL50060 - (3ph)	Polyphase Motor
TAL x46 G, KH02102Txxx, M2774L4, FGL50070 - (3ph)	Polyphase Motor
TAL x46 H, KH02103Txxx, M2776L4, FGL50080 - (3ph)	Polyphase Motor
TAL x47 A, M3115L4 - (3ph)	Polyphase Motor
TAL x47 B, M3134L4 - (3ph)	Polyphase Motor
TAL x47 C, M3136L4 - (3ph)	Polyphase Motor
TAL x47 D, M3134L4 - (3ph)	Polyphase Motor
TAL x47 E, M3156L4 - (3ph)	Polyphase Motor
TAL x47 F, M3175L4 - (3ph)	Polyphase Motor
TAL x473 A, M3115L41, FGL60010 - (3ph)	Polyphase Motor
TAL x473 A0 - (3ph)	Polyphase Motor
TAL x473 B, M3134L41, FGL60020 - (3ph)	Polyphase Motor
TAL x473 C, M3136L41, FGL60030 - (3ph)	Polyphase Motor
TAL x473 D, M3154L41, FGL60040 - (3ph)	Polyphase Motor
TAL x473 E, M3173L41, FGL60050 - (3ph)	Polyphase Motor
TAL x473 F, M3175L41, FGL60060 - (3ph)	Polyphase Motor
TAL x49 A - (3ph)	Polyphase Motor
TAL x49 B, FGL70020 - (3ph)	Polyphase Motor
TAL x49 C, FGL70030 - (3ph)	Polyphase Motor
TAL x49 D, FGL70040 - (3ph)	Polyphase Motor
TAL x49 E, FGL70050 - (3ph)	Polyphase Motor
TAL046 J	Polyphase Motor
Xxx15x4J	Polyphase Motor
1, Xxx15x4L	Polyphase Motor
Xxx15x4N	Polyphase Motor

B. Mahlen

Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number UL-US-L252760-12-41301102-2
 Report Reference E252760-20110314
 Date 4-Dec-2021

Xxx15x4P	Polyphase Motor
Xxx30x4B	Polyphase Motor
Xxx30x4D	Polyphase Motor
Xxx30x4E	Polyphase Motor
Xxx30x4F	Polyphase Motor
Xxx31x4J	Polyphase Motor
Xxx42.3Lx	Polyphase Motor
1, Xxx42.3Mx	Polyphase Motor
1, Xxx42.3S5	Polyphase Motor
71.2kW/4p/208V, Xxx43.2Lx, Xxx20x4J or Xxx20x4H	Polyphase Motor
72.8kW/4p/220V, Xxx43.2Lx, Xxx20x4J or Xxx20x4H	Polyphase Motor
74.4kW/4p/190V, Xxx43.2Lx, Xxx20x4J or Xxx20x4H	Polyphase Motor
75.2kW/4p/300V, Xxx43.2Lx, Xxx20x4J or Xxx20x4H	Polyphase Motor
64kW/4p/200V, Xxx43.2Lx, Xxx20x4J or Xxx20x4H	Polyphase Motor
77.6kW/4p/240V, Xxx43.2Lx, Xxx20x4J or Xxx20x4H	Polyphase Motor
54.4kW/4p/208V, Xxx43.2Mx or Xxx20x4F	Polyphase Motor
52.8kW/4p/220V, Xxx43.2Mx or Xxx20x4F	Polyphase Motor
54.4kW/4p/190V, Xxx43.2Mx or Xxx20x4F	Polyphase Motor
56kW/4p/300V, Xxx43.2Mx or Xxx20x4F	Polyphase Motor
48kW/4p/200V, Xxx43.2Mx or Xxx20x4F	Polyphase Motor
56.8kW/4p/240V, Xxx43.2Mx or Xxx20x4F	Polyphase Motor
50kW/4p/220V, Xxx43.2Sx, Xxx20x4D, Xxx20x4B or Xxx20x4C	Polyphase Motor
48.8kW/4p/190V, Xxx43.2Sx, Xxx20x4D, Xxx20x4B or Xxx20x4C	Polyphase Motor
48.8kW/4p/208V, Xxx43.2Sx, Xxx20x4D, Xxx20x4B or Xxx20x4C	Polyphase Motor
52kW/4p/300V, Xxx43.2Sx, Xxx20x4D, Xxx20x4B or Xxx20x4C	Polyphase Motor
42.4kW/4p/200V, Xxx43.2Sx, Xxx20x4D, Xxx20x4B or Xxx20x4C	Polyphase Motor
52.8kW/4p/240V, Xxx43.2Sx, Xxx20x4D, Xxx20x4B or Xxx20x4C	Polyphase Motor
70.4kW/4p/190V, Xxx43.2VLx or Xxx20x4L	Polyphase Motor
76kW/4p/208V, Xxx43.2VLx or Xxx20x4L	Polyphase Motor
84kW/4p/240V, Xxx43.2VLx or Xxx20x4L	Polyphase Motor
68kW/4p/200V, Xxx43.2VLx or Xxx20x4L	Polyphase Motor
81.6kW/4p/220V, Xxx43.2VLx or Xxx20x4L	Polyphase Motor
155.2kW/4p/300V, Xxx44.2Lxx or Xxx30x4H	Polyphase Motor
150kW/4p/208V, Xxx44.2Lxx or Xxx30x4H	Polyphase Motor
153.6kW/4p/220V, Xxx44.2Lxx or Xxx30x4H	Polyphase Motor
149.6kW/4p/190V, Xxx44.2Lxx or Xxx30x4H	Polyphase Motor
164.8kW/4p/240V, Xxx44.2Lxx or Xxx30x4H	Polyphase Motor
132kW/4p/200V, Xxx44.2Lxx or Xxx30x4H	Polyphase Motor
Xxx44.2Mx	Polyphase Motor

B. Mahlen

Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number UL-US-L252760-12-41301102-2
Report Reference E252760-20110314
Date 4-Dec-2021

144kW/4p/208V , Xxx44.2Mx, Xxx30x4F	Polyphase Motor
143.2kW/4p/220V , Xxx44.2Mx, Xxx30x4F	Polyphase Motor
144kW/4p/190V , Xxx44.2Mx, Xxx30x4F	Polyphase Motor
148kW/4p/300V , Xxx44.2Mx, Xxx30x4F	Polyphase Motor
150.4kW/4p/240V , Xxx44.2Mx, Xxx30x4F	Polyphase Motor
120kW/4p/200V , Xxx44.2Mx, Xxx30x4F	Polyphase Motor
Xxx44.2Sx	Polyphase Motor
117kW/4p/208V , Xxx44.2Sx, Xxx30x4D or Xxx30x4E	Polyphase Motor
124kW/4p/220V , Xxx44.2Sx, Xxx30x4D or Xxx30x4E	Polyphase Motor
122.4kW/4p/190V , Xxx44.2Sx, Xxx30x4D or Xxx30x4E	Polyphase Motor
126.4kW/4p/300V , Xxx44.2Sx, Xxx30x4D or Xxx30x4E	Polyphase Motor
135.2kW/4p/240V , Xxx44.2Sx, Xxx30x4D or Xxx30x4E	Polyphase Motor
108kW/4p/200V , Xxx44.2Sx, Xxx30x4D or Xxx30x4E	Polyphase Motor
Xxx44.2VSx	Polyphase Motor
148kW/4p/220V , Xxx44.3Lx	Polyphase Motor
Xxx44.3Lx, Xxx31x4J, Xxx31x4K, KH01340Txxx, KH01341Txxx - (3ph)	Polyphase Motor
128kW/4p/190V , Xxx44.3Mx, Xxx31x4G or Xxx31x4H	Polyphase Motor
135.2kW/4p/300V , Xxx44.3Mx, Xxx31x4G or Xxx31x4H	Polyphase Motor
135.2kW/4p/240V , Xxx44.3Mx, Xxx31x4G or Xxx31x4H	Polyphase Motor
128kW/4p/200V , Xxx44.3Mx, Xxx31x4G or Xxx31x4H	Polyphase Motor
135.2kW/4p/208V , Xxx44.3Mx, Xxx31x4G or Xxx31x4H	Polyphase Motor
128kW/4p/220V , Xxx44.3Mx, Xxx31x4G or Xxx31x4H	Polyphase Motor
116kW/4p/240V , Xxx44.3Sx, Xxx31x4D or Xxx31x4F	Polyphase Motor
112kW/4p/208V , Xxx44.3Sx, Xxx31x4D or Xxx31x4F	Polyphase Motor
92kW/4p/200V , Xxx44.3Sx, Xxx31x4D or Xxx31x4F	Polyphase Motor
108kW/4p/220V , Xxx44.3Sx, Xxx31x4D or Xxx31x4F	Polyphase Motor
112kW/4p/300V , Xxx44.3Sx, Xxx31x4D or Xxx31x4F	Polyphase Motor
104kW/4p/190V , Xxx44.3Sx, Xxx31x4D or Xxx31x4F	Polyphase Motor
Xxx44.3VLx, Xxx31x4L - (3ph)	Polyphase Motor
278.4kW/4p/300V , Xxx46.2Lx, Xxx50x4J or Xxx50x4H	Polyphase Motor
260.8kW/4p/416V , Xxx46.2Lx, Xxx50x4J or Xxx50x4H	Polyphase Motor
224kW/4p/208V , Xxx46.2Lx, Xxx50x4J or Xxx50x4H	Polyphase Motor
260kW/4p/190V , Xxx46.2Lx, Xxx50x4J or Xxx50x4H	Polyphase Motor
253kW/4p/208V , Xxx46.2Lx, Xxx50x4J or Xxx50x4H	Polyphase Motor
283.2kW/4p/240V , Xxx46.2Lx, Xxx50x4J or Xxx50x4H	Polyphase Motor
224kW/4p/200V , Xxx46.2Lx, Xxx50x4J or Xxx50x4H	Polyphase Motor
272.8kW/4p/220V , Xxx46.2Lx, Xxx50x4J or Xxx50x4H	Polyphase Motor
200kW/4p/300V , Xxx46.2Mx, Xxx50x4F or Xxx50x4D	Polyphase Motor
192kW/4p/208V , Xxx46.2Mx, Xxx50x4F or Xxx50x4D	Polyphase Motor
188.8kW/4p/220V , Xxx46.2Mx, Xxx50x4F or Xxx50x4D	Polyphase Motor
192kW/4p/190V , Xxx46.2Mx, Xxx50x4F or Xxx50x4D	Polyphase Motor
200kW/4p/240V , Xxx46.2Mx, Xxx50x4F or Xxx50x4D	Polyphase Motor
164kW/4p/200V , Xxx46.2Mx, Xxx50x4F or Xxx50x4D	Polyphase Motor
252kW/4p/200V , Xxx46.2VLxx or Xxx50x4L	Polyphase Motor

B. Mahrenholz

Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number UL-US-L252760-12-41301102-2
 Report Reference E252760-20110314
 Date 4-Dec-2021

305.6kW/4p/220V, Xxx46.2VLxx or Xxx50x4L	Polyphase Motor
286kW/4p/208V, Xxx46.2VLxx or Xxx50x4L	Polyphase Motor
304kW/4p/190V, Xxx46.2VLxx or Xxx50x4L	Polyphase Motor
304kW/4p/416V, Xxx46.2VLxx or Xxx50x4L	Polyphase Motor
312.8kW/4p/300V, Xxx46.2VLxx or Xxx50x4L	Polyphase Motor
240kW/4p/208V, Xxx46.2VLxx or Xxx50x4L	Polyphase Motor
318.4kW/4p/240V, Xxx46.2VLxx or Xxx50x4L	Polyphase Motor
Xxx46.3Lxx or Xxx51x4N	Polyphase Motor
Xxx46.3Mx or Xxx51x4J	Polyphase Motor
Xxx46.3Sx, Xxx51x4D, Xxx51x4F, Xxx51x4G or Xxx51x4H	Polyphase Motor
600kW/4p/208V, Xxx47.2Lx or Xxx61x4K	Polyphase Motor
480kW/4p/200V, Xxx47.2Lx or Xxx61x4K	Polyphase Motor
600kW/4p/240V, Xxx47.2Lx or Xxx61x4K	Polyphase Motor
560kW/4p/220V, Xxx47.2Lx or Xxx61x4K	Polyphase Motor
592kW/4p/300V, Xxx47.2Lx or Xxx61x4K	Polyphase Motor
592kW/4p/190V, Xxx47.2Lx or Xxx61x4K	Polyphase Motor
428kW/4p/440V, Xxx47.2Mx, Xxx61x4F, Xxx61x4G, Xxx61x4H or Xxx61x4J	Polyphase Motor
528kW/4p/220V, Xxx47.2Mx, Xxx61x4F, Xxx61x4G, Xxx61x4H or Xxx61x4J	Polyphase Motor
552kW/4p/300V, Xxx47.2Mx, Xxx61x4F, Xxx61x4G, Xxx61x4H or Xxx61x4J	Polyphase Motor
552kW/4p/240V, Xxx47.2Mx, Xxx61x4F, Xxx61x4G, Xxx61x4H or Xxx61x4J	Polyphase Motor
440kW/4p/190V, Xxx47.2Mx, Xxx61x4F, Xxx61x4G, Xxx61x4H or Xxx61x4J	Polyphase Motor
500kW/4p/208V, Xxx47.2Mx, Xxx61x4F, Xxx61x4G, Xxx61x4H or Xxx61x4J	Polyphase Motor
516kW/4p/416V, Xxx47.2Mx, Xxx61x4F, Xxx61x4G, Xxx61x4H or Xxx61x4J	Polyphase Motor
440kW/4p/208V, Xxx47.2Mx, Xxx61x4F, Xxx61x4G, Xxx61x4H or Xxx61x4J	Polyphase Motor
464kW/4p/190V, Xxx47.2Mx, Xxx61x4F, Xxx61x4G, Xxx61x4H or Xxx61x4J	Polyphase Motor
440kW/4p/200V, Xxx47.2Mx, Xxx61x4F, Xxx61x4G, Xxx61x4H or Xxx61x4J	Polyphase Motor
516kW/4p/380V, Xxx47.2Mx, Xxx61x4F, Xxx61x4G, Xxx61x4H or Xxx61x4J	Polyphase Motor
364kW/4p/208V, Xxx47.2Sx or Xxx61x4D	Polyphase Motor
440kW/4p/220V, Xxx47.2Sx or Xxx61x4D	Polyphase Motor
456kW/4p/240V, Xxx47.2Sx or Xxx61x4D	Polyphase Motor
456kW/4p/380V, Xxx47.2Sx or Xxx61x4D	Polyphase Motor
436kW/4p/208V, Xxx47.2Sx or Xxx61x4D	Polyphase Motor
364kW/4p/200V, Xxx47.2Sx or Xxx61x4D	Polyphase Motor
352kW/4p/440V, Xxx47.2Sx or Xxx61x4D	Polyphase Motor

B. Mahlen

Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number UL-US-L252760-12-41301102-2
Report Reference E252760-20110314
Date 4-Dec-2021

456kW/4p/300V, Xxx47.2Sx or Xxx61x4D	Polyphase Motor
392kW/4p/190V, Xxx47.2Sx or Xxx61x4D	Polyphase Motor
320kW/4p/200V, Xxx47.2VSx or Xxx61x4B	Polyphase Motor
372.8kW/4p/220V, Xxx47.2VSx or Xxx61x4B	Polyphase Motor
396kW/4p/240V, Xxx47.2VSx or Xxx61x4B	Polyphase Motor
396kW/4p/208V, Xxx47.2VSx or Xxx61x4B	Polyphase Motor
396kW/4p/190V, Xxx47.2VSx or Xxx61x4B	Polyphase Motor
384kW/4p/300V, Xxx47.2VSx or Xxx61x4B	Polyphase Motor
Xxx47.2VSx, Xxx61x4B, Xxx61x4C, KH01630Txxx, KH01741Txxx - 3ph)	Polyphase Motor
Xxx47.3Lx - (3ph)	Polyphase Motor
Xxx47.3Mx - (3ph)	Polyphase Motor
Xxx47.3Sx - (3ph)	Polyphase Motor
Xxx47.3VSx - (3ph)	Polyphase Motor
728kW/4p/200V, Xxx49.1Lx, Xxx70x4P, Xxx71x4P, 12x8 or xx44xLxxxx	Polyphase Motor
840kW/4p/220V, Xxx49.1Lx, Xxx70x4P, Xxx71x4P, 12x8 or xx44xLxxxx	Polyphase Motor
824kW/4p/190V, Xxx49.1Lx, Xxx70x4P, Xxx71x4P, 12x8 or xx44xLxxxx	Polyphase Motor
824kW/4p/208V, Xxx49.1Lx, Xxx70x4P, Xxx71x4P, 12x8 or xx44xLxxxx	Polyphase Motor
912kW/4p/300V, Xxx49.1Lx, Xxx70x4P, Xxx71x4P, 12x8 or xx44xLxxxx	Polyphase Motor
1000kW/4p/480V, Xxx49.1Lx, Xxx70x4P, Xxx71x4P, 12x8 or xx44xLxxxx	Polyphase Motor
800kW/4p/380V, Xxx49.1Lx, Xxx70x4P, Xxx71x4P, 12x8 or xx44xLxxxx	Polyphase Motor
865kW/4p/416V, Xxx49.1Lx, Xxx70x4P, Xxx71x4P, 12x8 or xx44xLxxxx	Polyphase Motor
920kW/4p/440V, Xxx49.1Lx, Xxx70x4P, Xxx71x4P, 12x8 or xx44xLxxxx	Polyphase Motor
800kW/4p/400V, Xxx49.1Lx, Xxx70x4P, Xxx71x4P, 12x8 or xx44xLxxxx	Polyphase Motor
712kW/4p/190V, Xxx49.1Lx, Xxx70x4P, Xxx71x4P, 12x8 or xx44xLxxxx	Polyphase Motor
874kW/4p/240V, Xxx49.1Lx, Xxx70x4P, Xxx71x4P, 12x8 or xx44xLxxxx	Polyphase Motor
640kW/4p/200V, Xxx49.1Mx, Xxx70x4L, Xxx70x4J, 12x6 or xx44xMxxxx	Polyphase Motor
784kW/4p/300V, Xxx49.1Mx, Xxx70x4L, Xxx70x4J, 12x6 or xx44xMxxxx	Polyphase Motor
784kW/4p/240V, Xxx49.1Mx, Xxx70x4L, Xxx70x4J, 12x6 or xx44xMxxxx	Polyphase Motor
784kW/4p/208V, Xxx49.1Mx, Xxx70x4L, Xxx70x4J, 12x6 or xx44xMxxxx	Polyphase Motor

B. Mahlen

Bruce Mahlenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number UL-US-L252760-12-41301102-2
Report Reference E252760-20110314
Date 4-Dec-2021

784kW/4p/220V, Xxx49.1Mx, Xxx70x4L, Xxx70x4J, 12x6 or xx44xMxxxx	Polyphase Motor
784kW/4p/190V, Xxx49.1Mx, Xxx70x4L, Xxx70x4J, 12x6 or xx44xMxxxx	Polyphase Motor
528kW/4p/200V, Xxx49.1Sx, Xxx70x4D, Xxx70x4F or Xxx70x4H	Polyphase Motor
656kW/4p/300V, Xxx49.1Sx, Xxx70x4D, Xxx70x4F or Xxx70x4H	Polyphase Motor
656kW/4p/240V, Xxx49.1Sx, Xxx70x4D, Xxx70x4F or Xxx70x4H	Polyphase Motor
656kW/4p/190V, Xxx49.1Sx, Xxx70x4D, Xxx70x4F or Xxx70x4H	Polyphase Motor
656kW/4p/208V, Xxx49.1Sx, Xxx70x4D, Xxx70x4F or Xxx70x4H	Polyphase Motor
656kW/4p/220V, Xxx49.1Sx, Xxx70x4D, Xxx70x4F or Xxx70x4H	Polyphase Motor
Xxx49.3Lx, Xxx72x4N, Xxx72x4P, KH00390Txxx, KH03542Txxx - (3ph)	Polyphase Motor
Xxx49.3Mx, Xxx72x4J, Xxx72x4L, KH02850Txxx, KH03003Txxx - (3ph)	Polyphase Motor
Xxx49.3Sx, Xxx72x4H, KH02401Txxx - (3ph)	Polyphase Motor
xxx4P3.x-0001 to 1260	Polyphase Motor
xxx4P3.x-1261 to 2050	Polyphase Motor
1500kW/4p/208V, xxx4P5.x-xxxx	Polyphase Motor
xxx4P8.x-3450	Polyphase Motor
xxx4P9.x-0001 to 1800 CACA	Polyphase Motor
xxx4P9.x-0001 to 1800, xx94xSxxxx, xx94xLxxxx, 30xx, or 31xx	Polyphase Motor
xxx4P9.x-1801 to 2100 CACA	Polyphase Motor
xxx4P9.x-1801 to 2100, xx94xSxxxx, xx94xLxxxx, 30xx, or 31xx	Polyphase Motor
xxx4P9.x-2101 to 2250, xx94xMxxxx, xx94xVLxxxx, 30xx, or 31xx	Polyphase Motor
xxx4P9.x-2101 to 2400 CACA	Polyphase Motor
xxx4P9.x-2251 to 2400, xx94xMxxxx, xx94xVLxxxx, 30xx, or 31xx	Polyphase Motor
xxx4P9.x-2401 to 2700 CACA	Polyphase Motor
xxx4P9.x-2401 to 2700, xx94xMxxxx, xx94xVLxxxx, 30xx, or 31xx	Polyphase Motor
xxx4P9.x-2701 to 2950 CACA	Polyphase Motor
xxx4P9.x-2701 to 2950, xx94xLxxxx, 30xx, or 31xx	Polyphase Motor
xxx4P9.x-2951 to 3200 CACA	Polyphase Motor
xxx4P9.x-2951 to 3200, xx94xLxxxx, 30xx, or 31xx	Polyphase Motor
1500kW/4p/208V, Xxx50.2Lx	Polyphase Motor
1500kW/4p/240V, Xxx50.2Lx, Xxx82x4L, Xxx82x4N, 144x-xxx, xxx4P5.x-xxxx, xxx54xLxx	Polyphase Motor

B. Mahlen

Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number UL-US-L252760-12-41301102-2
Report Reference E252760-20110314
Date 4-Dec-2021

1500kW/4p/300V, Xxx50.2Lx, Xxx82x4L, Xxx82x4N, 144x-xxx, xxx4P5.x-xxxx, xxx54xLxx	Polyphase Motor
1500kW/4p/220V, Xxx50.2Lx, Xxx82x4L, Xxx82x4N, 144x-xxx, xxx4P5.x-xxxx, xxx54xLxx	Polyphase Motor
1200kW/4p/200V, Xxx50.2Lx, Xxx82x4L, Xxx82x4N, 144x-xxx, xxx4P5.x-xxxx, xxx54xLxx	Polyphase Motor
1376kW/4p/190V, Xxx50.2Lx, Xxx82x4L, Xxx82x4N, 144x-xxx, xxx4P5.x-xxxx, xxx54xLxx	Polyphase Motor
1272kW/4p/300V, Xxx50.2Mx, Xxx82x4H, 142x-xxx, xxx4P5.x-xxxx or xxx54xMxx	Polyphase Motor
1240kW/4p/220V, Xxx50.2Mx, Xxx82x4H, 142x-xxx, xxx4P5.x-xxxx or xxx54xMxx	Polyphase Motor
1240kW/4p/208V, Xxx50.2Mx, Xxx82x4H, 142x-xxx, xxx4P5.x-xxxx or xxx54xMxx	Polyphase Motor
1272kW/4p/240V, Xxx50.2Mx, Xxx82x4H, 142x-xxx, xxx4P5.x-xxxx or xxx54xMxx	Polyphase Motor
1060kW/4p/200V, Xxx50.2Mx, Xxx82x4H, 142x-xxx, xxx4P5.x-xxxx or xxx54xMxx	Polyphase Motor
1200kW/4p/190V, Xxx50.2Mx, Xxx82x4H, 142x-xxx, xxx4P5.x-xxxx or xxx54xMxx	Polyphase Motor
1040kW/4p/300V, Xxx50.2Sx, Xxx82x4A, Xxx82x4B, 140x-xxx, xxx4P5.x-xxxx, xxx54xSxxx	Polyphase Motor
1040kW/4p/220V, Xxx50.2Sx, Xxx82x4A, Xxx82x4B, 140x-xxx, xxx4P5.x-xxxx, xxx54xSxxx	Polyphase Motor
1040kW/4p/208V, Xxx50.2Sx, Xxx82x4A, Xxx82x4B, 140x-xxx, xxx4P5.x-xxxx, xxx54xSxxx	Polyphase Motor
1040kW/4p/240V, Xxx50.2Sx, Xxx82x4A, Xxx82x4B, 140x-xxx, xxx4P5.x-xxxx, xxx54xSxxx	Polyphase Motor
832kW/4p/200V, Xxx50.2Sx, Xxx82x4A, Xxx82x4B, 140x-xxx, xxx4P5.x-xxxx, xxx54xSxxx	Polyphase Motor
992kW/4p/190V, Xxx50.2Sx, Xxx82x4A, Xxx82x4B, 140x-xxx, xxx4P5.x-xxxx, xxx54xSxxx	Polyphase Motor
1600kW/4p/240V, Xxx50.2VLxx, Xxx82x4P, 146x-xxx, 148x-xxx, xxx4P5.x-xxxx or xxx54xVLxx	Polyphase Motor
1600kW/4p/300V, Xxx50.2VLxx, Xxx82x4P, 146x-xxx, 148x-xxx, xxx4P5.x-xxxx or xxx54xVLxx	Polyphase Motor
1600kW/4p/208V, Xxx50.2VLxx, Xxx82x4P, 146x-xxx, 148x-xxx, xxx4P5.x-xxxx or xxx54xVLxx	Polyphase Motor
1600kW/4p/220V, Xxx50.2VLxx, Xxx82x4P, 146x-xxx, 148x-xxx, xxx4P5.x-xxxx or xxx54xVLxx	Polyphase Motor
1312kW/4p/200V, Xxx50.2VLxx, Xxx82x4P, 146x-xxx, 148x-xxx, xxx4P5.x-xxxx or xxx54xVLxx	Polyphase Motor
1476kW/4p/190V, Xxx50.2VLxx, Xxx82x4P, 146x-xxx, 148x-xxx, xxx4P5.x-xxxx or xxx54xVLxx	Polyphase Motor
1600kW/4p/240V, Xxx50.xXLx, 148x-xxx, xxx4P5.x-xxxx or xxx54xXLxx	Polyphase Motor

B. Mahlen

Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number UL-US-L252760-12-41301102-2
Report Reference E252760-20110314
Date 4-Dec-2021

1600kW/4p/300V, Xxx50.xXLx, 148x-xxx, xxx4P5.x-xxxx or xxx54xXLxx	Polyphase Motor
1600kW/4p/208V, Xxx50.xXLx, 148x-xxx, xxx4P5.x-xxxx or xxx54xXLxx	Polyphase Motor
1600kW/4p/220V, Xxx50.xXLx, 148x-xxx, xxx4P5.x-xxxx or xxx54xXLxx	Polyphase Motor
1312kW/4p/200V, Xxx50.xXLx, 148x-xxx, xxx4P5.x-xxxx or xxx54xXLxx	Polyphase Motor
1476kW/4p/190V, Xxx50.xXLx, 148x-xxx, xxx4P5.x-xxxx or xxx54xXLxx	Polyphase Motor
1728kW/4p/200V, Xxx51.xLxx, Xxx9xx4L, 164x-xxx, xxx4P6.x-xxxx or xxx64xLxx	Polyphase Motor
2150.4kW/4p/240V, Xxx51.xLxx, Xxx9xx4L, 164x-xxx, xxx4P6.x-xxxx or xxx64xLxx	Polyphase Motor
2150.4kW/4p/300V, Xxx51.xLxx, Xxx9xx4L, 164x-xxx, xxx4P6.x-xxxx or xxx64xLxx	Polyphase Motor
2065kW/4p/208V, Xxx51.xLxx, Xxx9xx4L, 164x-xxx, xxx4P6.x-xxxx or xxx64xLxx	Polyphase Motor
2065kW/4p/190V, Xxx51.xLxx, Xxx9xx4L, 164x-xxx, xxx4P6.x-xxxx or xxx64xLxx	Polyphase Motor
2065kW/4p/220V, Xxx51.xLxx, Xxx9xx4L, 164x-xxx, xxx4P6.x-xxxx or xxx64xLxx	Polyphase Motor
1920kW/4p/220V, Xxx51.xMxx, Xxx9xx4H, 162x-xxx, Xxx4P6.x-xxxx or Xxx64xMxx	Polyphase Motor
2000kW/4p/240V, Xxx51.xMxx, Xxx9xx4H, 162x-xxx, Xxx4P6.x-xxxx or Xxx64xMxx	Polyphase Motor
1885kW/4p/190V, Xxx51.xMxx, Xxx9xx4H, 162x-xxx, Xxx4P6.x-xxxx or Xxx64xMxx	Polyphase Motor
1920kW/4p/208V, Xxx51.xMxx, Xxx9xx4H, 162x-xxx, Xxx4P6.x-xxxx or Xxx64xMxx	Polyphase Motor
1640kW/4p/200V, Xxx51.xMxx, Xxx9xx4H, 162x-xxx, Xxx4P6.x-xxxx or Xxx64xMxx	Polyphase Motor
2000kW/4p/300V, Xxx51.xMxx, Xxx9xx4H, 162x-xxx, Xxx4P6.x-xxxx or Xxx64xMxx	Polyphase Motor
1800kW/4p/240V, Xxx51.xSxx, Xxx9xx4F, 160x-xxx, xxx4P6.x-xxxx or xxx64xSxx	Polyphase Motor
1800kW/4p/300V, Xxx51.xSxx, Xxx9xx4F, 160x-xxx, xxx4P6.x-xxxx or xxx64xSxx	Polyphase Motor
1728kW/4p/208V, Xxx51.xSxx, Xxx9xx4F, 160x-xxx, xxx4P6.x-xxxx or xxx64xSxx	Polyphase Motor
1650kW/4p/190V, Xxx51.xSxx, Xxx9xx4F, 160x-xxx, xxx4P6.x-xxxx or xxx64xSxx	Polyphase Motor
1728kW/4p/220V, Xxx51.xSxx, Xxx9xx4F, 160x-xxx, xxx4P6.x-xxxx or xxx64xSxx	Polyphase Motor
1488kW/4p/200V, Xxx51.xSxx, Xxx9xx4F, 160x-xxx, xxx4P6.x-xxxx or xxx64xSxx	Polyphase Motor

B. Mahlen

Bruce Mahlenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number UL-US-L252760-12-41301102-2
Report Reference E252760-20110314
Date 4-Dec-2021

1800kW/4p/200V , Xxx51.xVLxx, Xxx9xx4P, 166x-xxx, xxx4P6.x-xxxx or xxx64xVLxx	Polyphase Motor
2250.4kW/4p/240V , Xxx51.xVLxx, Xxx9xx4P, 166x-xxx, xxx4P6.x-xxxx or xxx64xVLxx	Polyphase Motor
2250.4kW/4p/300V , Xxx51.xVLxx, Xxx9xx4P, 166x-xxx, xxx4P6.x-xxxx or xxx64xVLxx	Polyphase Motor
1952kW/4p/208V , Xxx51.xVLxx, Xxx9xx4P, 166x-xxx, xxx4P6.x-xxxx or xxx64xVLxx	Polyphase Motor
1800kW/4p/190V , Xxx51.xVLxx, Xxx9xx4P, 166x-xxx, xxx4P6.x-xxxx or xxx64xVLxx	Polyphase Motor
2068kW/4p/220V , Xxx51.xVLxx, Xxx9xx4P, 166x-xxx, xxx4P6.x-xxxx or xxx64xVLxx	Polyphase Motor
52 , xxx52.xLxx, xxx9xx4x, xx4P6.x-xxxx, or xxx64xLxx	Polyphase Motor
52 , xxx52.xSxx, xxx9xx4x, xx4P6.x-xxxx, or xxx64xSxx	Polyphase Motor
1500kW/4p/208V , xxx54xLxx	Polyphase Motor
1500kW/4p/208V , Xxx82x4L	Polyphase Motor
1500kW/4p/208V , Xxx82x4N	Polyphase Motor
xxx84xULxx	Polyphase Motor



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number UL-CA-L252760-32-41301102-2
Report Reference E252760-20110314
Date 4-Dec-2021

Issued to: LEROY SOMER
669 NATCHEZ TRACE DR LEXINGTON, TN
United States 38351-4125

This is to certify that JZGZ7 - Generators Certified for Canada
representative samples of See Addendum Page for Product Designation(s).

Have been investigated by UL in accordance with the
Standard(s) indicated on this Certificate.

Standard(s) for Safety: CSA C22.2 NO. 100, 7th Ed., Issue Date: 2014-07-01,
Revision Date: 2017-04-01

Additional Information: See the UL Online Certifications Directory at
<https://iq.ulprospector.com> for additional information

This Certificate of Compliance does not provide authorization to apply the UL Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.

B. Mahlen

Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number UL-CA-L252760-32-41301102-2
 Report Reference E252760-20110314
 Date 4-Dec-2021

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements

Model	Category Description
1500kW/4p/208V, 144x-xxx	Polyphase Motor
2130kW/6p/600V, 17xx, Xxx6P6/x-xxxx or Xxx66x-xx	Polyphase Motor
187x	Polyphase Motor
4P8-1, 182x, 184x, xxx4P8.x-xxxx or xxx84xVSxx	Polyphase Motor
4P8-2, 182x, 184x, xxx4P8.x-xxxx or xxx84xSxx	Polyphase Motor
4P8-3, 182x, 184x, xxx4P8.x-xxxx or xxx84xMxx	Polyphase Motor
4P8-4, 182x, 184x, xxx4P8.x-xxxx or xxx84xLxx	Polyphase Motor
4P8-5, 182x, 184x, xxx4P8.x-xxxx or xxx84xVLxx	Polyphase Motor
4P8-6	Polyphase Motor
KH00390Txxx	Polyphase Motor
KH00590Txxx	Polyphase Motor
KH00591Txxx	Polyphase Motor
KH00601Txxx	Polyphase Motor
KH00602Txxx	Polyphase Motor
KH00682Txxx	Polyphase Motor
KH00720Txxx	Polyphase Motor
KH00721Txxx	Polyphase Motor
KH00750Txxx	Polyphase Motor
KH00751Txxx	Polyphase Motor
KH00752Txxx	Polyphase Motor
KH00753Txxx	Polyphase Motor
KH00810Txxx	Polyphase Motor
KH00811Txxx	Polyphase Motor
KH00900Txxx	Polyphase Motor
KH00910Txxx	Polyphase Motor
KH00911Txxx	Polyphase Motor
KH01050Txxx	Polyphase Motor
KH01051Txxx	Polyphase Motor
KH01052Txxx	Polyphase Motor
KH01100Txx	Polyphase Motor
KH01130Txxx	Polyphase Motor
KH01131Txxx	Polyphase Motor
KH01132Txxx	Polyphase Motor
KH01190Txxx	Polyphase Motor
KH01220Txxx	Polyphase Motor
KH01310Txxx	Polyphase Motor
KH01341Txxx	Polyphase Motor
KH01370Txxx	Polyphase Motor
KH01420Txxx	Polyphase Motor

B. Mahlen

Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number UL-CA-L252760-32-41301102-2
 Report Reference E252760-20110314
 Date 4-Dec-2021

KH01421Txxx	Polyphase Motor
KH01512Txxx	Polyphase Motor
KH01600Txxx	Polyphase Motor
KH01640Txxx	Polyphase Motor
KH01641Txxx	Polyphase Motor
KH01741Txxx	Polyphase Motor
KH01800Txxx	Polyphase Motor
KH02070Txxx	Polyphase Motor
KH02100Txxx	Polyphase Motor
KH02101Txxx	Polyphase Motor
KH02260Txxx	Polyphase Motor
KH02400Txxx	Polyphase Motor
KH02401Txxx	Polyphase Motor
KH02450Txxx	Polyphase Motor
KH02460Txxx	Polyphase Motor
KH02610Txxx	Polyphase Motor
KH02850Txxx	Polyphase Motor
KH02880Txxx	Polyphase Motor
KH02971Txxx	Polyphase Motor
KH03000Txxx	Polyphase Motor
KH03001Txxx	Polyphase Motor
KH03002Txxx	Polyphase Motor
KH03003Txxx	Polyphase Motor
KH03541Txxx	Polyphase Motor
KH03542Txxx	Polyphase Motor
KH03600Txxx	Polyphase Motor
KH03601Txxx	Polyphase Motor
KH03602Txxx	Polyphase Motor
KH03603Txxx	Polyphase Motor
KH03890Txxx	Polyphase Motor
KH04450Txxx	Polyphase Motor
KH05090Txxx	Polyphase Motor
M2732L4	Polyphase Motor
M2734L4	Polyphase Motor
M2736L4	Polyphase Motor
M2738L4	Polyphase Motor
M2754L4	Polyphase Motor
M2756L4	Polyphase Motor
M2774L4	Polyphase Motor
3ph, M2776L4	Polyphase Motor
M3115L4	Polyphase Motor
3ph, M3134L4	Polyphase Motor
phase 3, M3136L4	Polyphase Motor
M3154L4	Polyphase Motor
M3156L4	Polyphase Motor

B. Mahlen

Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number UL-CA-L252760-32-41301102-2
Report Reference E252760-20110314
Date 4-Dec-2021

M3175L4	Polyphase Motor
TAL x42 E, KH00602Txxx, M1736L4, FGL20050 - (3ph)	Polyphase Motor
TAL x42 F, M1754L4, FGL20060 - (3ph)	Polyphase Motor
TAL x42 G, KH00721Txxx, M1756L4, FGL20070 - (3ph)	Polyphase Motor
TAL x42 H, KH00811Txxx, M1775L4, FGL20080 - (3ph)	Polyphase Motor
TAL x44 A, KH00591Txxx, FGL30010 - (3ph)	Polyphase Motor
TAL x44 B, KH00590Txxx, M2233L4, FGL30020 - (3ph)	Polyphase Motor
TAL x44 C, KH00752Txxx, M2235L4, FGL30030 - (3ph)	Polyphase Motor
TAL x44 D, KH00753Txxx, M2236L4, FGL30040 - (3ph)	Polyphase Motor
TAL x44 E, KH01051Txxx, FGL30050 - (3ph)	Polyphase Motor
TAL x44 H, KH01052Txxx, M2254L4, FGL30080 - (3ph)	Polyphase Motor
TAL x44 J, KH01191Txxx, M2256L4, FGL30100 - (3ph)	Polyphase Motor
TAL x44 K, KH01340Txxx, M2275L4, FGL30110 - (3ph)	Polyphase Motor
TAL x44 L, KH01680Txxx, M2294L4, FGL30120 - (3ph)	Polyphase Motor
TAL x44 M, KH01681Txxx, FGL30130 - (3ph)	Polyphase Motor
TAL x46 A, M2732L4 - (3ph)	Polyphase Motor
TAL x46 B, M2734L4 - (3ph)	Polyphase Motor
TAL x46 C, KH01221Txxx, M2736L4, FGL50030 - (3ph)	Polyphase Motor
TAL x46 D, KH01222Txx, M2738L4, FGL50040 - (3ph)	Polyphase Motor
TAL x46 E, KH01642Txxx, M2754L4, FGL50050 - (3ph)	Polyphase Motor
TAL x46 F, KH01643Txxx, M2756L4, FGL50060 - (3ph)	Polyphase Motor
TAL x46 G, KH02102Txxx, M2774L4, FGL50070 - (3ph)	Polyphase Motor
TAL x46 H, KH02103Txxx, M2776L4, FGL50080 - (3ph)	Polyphase Motor
TAL x47 A, M3115L4 - (3ph)	Polyphase Motor
TAL x47 B, M3134L4 - (3ph)	Polyphase Motor
TAL x47 C, M3136L4 - (3ph)	Polyphase Motor
TAL x47 D, M3134L4 - (3ph)	Polyphase Motor
TAL x47 E, M3156L4 - (3ph)	Polyphase Motor
TAL x47 F, M3175L4 - (3ph)	Polyphase Motor
TAL x473 A, M3115L41, FGL60010 - (3ph)	Polyphase Motor
TAL x473 A0 - (3ph)	Polyphase Motor
TAL x473 B, M3134L41, FGL60020 - (3ph)	Polyphase Motor
TAL x473 C, M3136L41, FGL60030 - (3ph)	Polyphase Motor
TAL x473 D, M3154L41, FGL60040 - (3ph)	Polyphase Motor
TAL x473 E, M3173L41, FGL60050 - (3ph)	Polyphase Motor
TAL x473 F, M3175L41, FGL60060 - (3ph)	Polyphase Motor
TAL x49 A - (3ph)	Polyphase Motor
TAL x49 B, FGL70020 - (3ph)	Polyphase Motor
TAL x49 C, FGL70030 - (3ph)	Polyphase Motor
TAL x49 D, FGL70040 - (3ph)	Polyphase Motor
TAL x49 E, FGL70050 - (3ph)	Polyphase Motor
TAL046 J	Polyphase Motor
Xxx15x4J	Polyphase Motor
1, Xxx15x4L	Polyphase Motor
Xxx15x4N	Polyphase Motor

B. Mahlen

Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number UL-CA-L252760-32-41301102-2
 Report Reference E252760-20110314
 Date 4-Dec-2021

Xxx15x4P	Polyphase Motor
Xxx30x4B	Polyphase Motor
Xxx30x4D	Polyphase Motor
Xxx30x4E	Polyphase Motor
Xxx30x4F	Polyphase Motor
Xxx31x4J	Polyphase Motor
Xxx42.3Lx	Polyphase Motor
1, Xxx42.3Mx	Polyphase Motor
1, Xxx42.3S5	Polyphase Motor
71.2kW/4p/208V, Xxx43.2Lx, Xxx20x4J or Xxx20x4H	Polyphase Motor
72.8kW/4p/220V, Xxx43.2Lx, Xxx20x4J or Xxx20x4H	Polyphase Motor
74.4kW/4p/190V, Xxx43.2Lx, Xxx20x4J or Xxx20x4H	Polyphase Motor
75.2kW/4p/300V, Xxx43.2Lx, Xxx20x4J or Xxx20x4H	Polyphase Motor
64kW/4p/200V, Xxx43.2Lx, Xxx20x4J or Xxx20x4H	Polyphase Motor
77.6kW/4p/240V, Xxx43.2Lx, Xxx20x4J or Xxx20x4H	Polyphase Motor
54.4kW/4p/208V, Xxx43.2Mx or Xxx20x4F	Polyphase Motor
52.8kW/4p/220V, Xxx43.2Mx or Xxx20x4F	Polyphase Motor
54.4kW/4p/190V, Xxx43.2Mx or Xxx20x4F	Polyphase Motor
56kW/4p/300V, Xxx43.2Mx or Xxx20x4F	Polyphase Motor
48kW/4p/200V, Xxx43.2Mx or Xxx20x4F	Polyphase Motor
56.8kW/4p/240V, Xxx43.2Mx or Xxx20x4F	Polyphase Motor
50kW/4p/220V, Xxx43.2Sx, Xxx20x4D, Xxx20x4B or Xxx20x4C	Polyphase Motor
48.8kW/4p/190V, Xxx43.2Sx, Xxx20x4D, Xxx20x4B or Xxx20x4C	Polyphase Motor
48.8kW/4p/208V, Xxx43.2Sx, Xxx20x4D, Xxx20x4B or Xxx20x4C	Polyphase Motor
52kW/4p/300V, Xxx43.2Sx, Xxx20x4D, Xxx20x4B or Xxx20x4C	Polyphase Motor
42.4kW/4p/200V, Xxx43.2Sx, Xxx20x4D, Xxx20x4B or Xxx20x4C	Polyphase Motor
52.8kW/4p/240V, Xxx43.2Sx, Xxx20x4D, Xxx20x4B or Xxx20x4C	Polyphase Motor
70.4kW/4p/190V, Xxx43.2VLx or Xxx20x4L	Polyphase Motor
76kW/4p/208V, Xxx43.2VLx or Xxx20x4L	Polyphase Motor
84kW/4p/240V, Xxx43.2VLx or Xxx20x4L	Polyphase Motor
68kW/4p/200V, Xxx43.2VLx or Xxx20x4L	Polyphase Motor
81.6kW/4p/220V, Xxx43.2VLx or Xxx20x4L	Polyphase Motor
155.2kW/4p/300V, Xxx44.2Lxx or Xxx30x4H	Polyphase Motor
150kW/4p/208V, Xxx44.2Lxx or Xxx30x4H	Polyphase Motor
153.6kW/4p/220V, Xxx44.2Lxx or Xxx30x4H	Polyphase Motor
149.6kW/4p/190V, Xxx44.2Lxx or Xxx30x4H	Polyphase Motor
164.8kW/4p/240V, Xxx44.2Lxx or Xxx30x4H	Polyphase Motor
132kW/4p/200V, Xxx44.2Lxx or Xxx30x4H	Polyphase Motor
Xxx44.2Mx	Polyphase Motor

B. Mahlen

Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number UL-CA-L252760-32-41301102-2
 Report Reference E252760-20110314
 Date 4-Dec-2021

144kW/4p/208V , Xxx44.2Mx, Xxx30x4F	Polyphase Motor
143.2kW/4p/220V , Xxx44.2Mx, Xxx30x4F	Polyphase Motor
144kW/4p/190V , Xxx44.2Mx, Xxx30x4F	Polyphase Motor
148kW/4p/300V , Xxx44.2Mx, Xxx30x4F	Polyphase Motor
150.4kW/4p/240V , Xxx44.2Mx, Xxx30x4F	Polyphase Motor
120kW/4p/200V , Xxx44.2Mx, Xxx30x4F	Polyphase Motor
Xxx44.2Sx	Polyphase Motor
117kW/4p/208V , Xxx44.2Sx, Xxx30x4D or Xxx30x4E	Polyphase Motor
124kW/4p/220V , Xxx44.2Sx, Xxx30x4D or Xxx30x4E	Polyphase Motor
122.4kW/4p/190V , Xxx44.2Sx, Xxx30x4D or Xxx30x4E	Polyphase Motor
126.4kW/4p/300V , Xxx44.2Sx, Xxx30x4D or Xxx30x4E	Polyphase Motor
135.2kW/4p/240V , Xxx44.2Sx, Xxx30x4D or Xxx30x4E	Polyphase Motor
108kW/4p/200V , Xxx44.2Sx, Xxx30x4D or Xxx30x4E	Polyphase Motor
Xxx44.2VSx	Polyphase Motor
148kW/4p/220V , Xxx44.3Lx	Polyphase Motor
Xxx44.3Lx, Xxx31x4J, Xxx31x4K, KH01340Txxx, KH01341Txxx - (3ph)	Polyphase Motor
128kW/4p/190V , Xxx44.3Mx, Xxx31x4G or Xxx31x4H	Polyphase Motor
135.2kW/4p/300V , Xxx44.3Mx, Xxx31x4G or Xxx31x4H	Polyphase Motor
135.2kW/4p/240V , Xxx44.3Mx, Xxx31x4G or Xxx31x4H	Polyphase Motor
128kW/4p/200V , Xxx44.3Mx, Xxx31x4G or Xxx31x4H	Polyphase Motor
135.2kW/4p/208V , Xxx44.3Mx, Xxx31x4G or Xxx31x4H	Polyphase Motor
128kW/4p/220V , Xxx44.3Mx, Xxx31x4G or Xxx31x4H	Polyphase Motor
116kW/4p/240V , Xxx44.3Sx, Xxx31x4D or Xxx31x4F	Polyphase Motor
112kW/4p/208V , Xxx44.3Sx, Xxx31x4D or Xxx31x4F	Polyphase Motor
92kW/4p/200V , Xxx44.3Sx, Xxx31x4D or Xxx31x4F	Polyphase Motor
108kW/4p/220V , Xxx44.3Sx, Xxx31x4D or Xxx31x4F	Polyphase Motor
112kW/4p/300V , Xxx44.3Sx, Xxx31x4D or Xxx31x4F	Polyphase Motor
104kW/4p/190V , Xxx44.3Sx, Xxx31x4D or Xxx31x4F	Polyphase Motor
Xxx44.3VLx, Xxx31x4L - (3ph)	Polyphase Motor
278.4kW/4p/300V , Xxx46.2Lx, Xxx50x4J or Xxx50x4H	Polyphase Motor
260.8kW/4p/416V , Xxx46.2Lx, Xxx50x4J or Xxx50x4H	Polyphase Motor
224kW/4p/208V , Xxx46.2Lx, Xxx50x4J or Xxx50x4H	Polyphase Motor
260kW/4p/190V , Xxx46.2Lx, Xxx50x4J or Xxx50x4H	Polyphase Motor
253kW/4p/208V , Xxx46.2Lx, Xxx50x4J or Xxx50x4H	Polyphase Motor
283.2kW/4p/240V , Xxx46.2Lx, Xxx50x4J or Xxx50x4H	Polyphase Motor
224kW/4p/200V , Xxx46.2Lx, Xxx50x4J or Xxx50x4H	Polyphase Motor
272.8kW/4p/220V , Xxx46.2Lx, Xxx50x4J or Xxx50x4H	Polyphase Motor
200kW/4p/300V , Xxx46.2Mx, Xxx50x4F or Xxx50x4D	Polyphase Motor
192kW/4p/208V , Xxx46.2Mx, Xxx50x4F or Xxx50x4D	Polyphase Motor
188.8kW/4p/220V , Xxx46.2Mx, Xxx50x4F or Xxx50x4D	Polyphase Motor
192kW/4p/190V , Xxx46.2Mx, Xxx50x4F or Xxx50x4D	Polyphase Motor
200kW/4p/240V , Xxx46.2Mx, Xxx50x4F or Xxx50x4D	Polyphase Motor
164kW/4p/200V , Xxx46.2Mx, Xxx50x4F or Xxx50x4D	Polyphase Motor
252kW/4p/200V , Xxx46.2VLxx or Xxx50x4L	Polyphase Motor

B. Mahrenholz

Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number UL-CA-L252760-32-41301102-2
 Report Reference E252760-20110314
 Date 4-Dec-2021

305.6kW/4p/220V, Xxx46.2VLxx or Xxx50x4L	Polyphase Motor
286kW/4p/208V, Xxx46.2VLxx or Xxx50x4L	Polyphase Motor
304kW/4p/190V, Xxx46.2VLxx or Xxx50x4L	Polyphase Motor
304kW/4p/416V, Xxx46.2VLxx or Xxx50x4L	Polyphase Motor
312.8kW/4p/300V, Xxx46.2VLxx or Xxx50x4L	Polyphase Motor
240kW/4p/208V, Xxx46.2VLxx or Xxx50x4L	Polyphase Motor
318.4kW/4p/240V, Xxx46.2VLxx or Xxx50x4L	Polyphase Motor
Xxx46.3Lxx or Xxx51x4N	Polyphase Motor
Xxx46.3Mx or Xxx51x4J	Polyphase Motor
Xxx46.3Sx, Xxx51x4D, Xxx51x4F, Xxx51x4G or Xxx51x4H	Polyphase Motor
600kW/4p/208V, Xxx47.2Lx or Xxx61x4K	Polyphase Motor
480kW/4p/200V, Xxx47.2Lx or Xxx61x4K	Polyphase Motor
600kW/4p/240V, Xxx47.2Lx or Xxx61x4K	Polyphase Motor
560kW/4p/220V, Xxx47.2Lx or Xxx61x4K	Polyphase Motor
592kW/4p/300V, Xxx47.2Lx or Xxx61x4K	Polyphase Motor
592kW/4p/190V, Xxx47.2Lx or Xxx61x4K	Polyphase Motor
428kW/4p/440V, Xxx47.2Mx, Xxx61x4F, Xxx61x4G, Xxx61x4H or Xxx61x4J	Polyphase Motor
528kW/4p/220V, Xxx47.2Mx, Xxx61x4F, Xxx61x4G, Xxx61x4H or Xxx61x4J	Polyphase Motor
552kW/4p/300V, Xxx47.2Mx, Xxx61x4F, Xxx61x4G, Xxx61x4H or Xxx61x4J	Polyphase Motor
552kW/4p/240V, Xxx47.2Mx, Xxx61x4F, Xxx61x4G, Xxx61x4H or Xxx61x4J	Polyphase Motor
440kW/4p/190V, Xxx47.2Mx, Xxx61x4F, Xxx61x4G, Xxx61x4H or Xxx61x4J	Polyphase Motor
500kW/4p/208V, Xxx47.2Mx, Xxx61x4F, Xxx61x4G, Xxx61x4H or Xxx61x4J	Polyphase Motor
516kW/4p/416V, Xxx47.2Mx, Xxx61x4F, Xxx61x4G, Xxx61x4H or Xxx61x4J	Polyphase Motor
440kW/4p/208V, Xxx47.2Mx, Xxx61x4F, Xxx61x4G, Xxx61x4H or Xxx61x4J	Polyphase Motor
464kW/4p/190V, Xxx47.2Mx, Xxx61x4F, Xxx61x4G, Xxx61x4H or Xxx61x4J	Polyphase Motor
440kW/4p/200V, Xxx47.2Mx, Xxx61x4F, Xxx61x4G, Xxx61x4H or Xxx61x4J	Polyphase Motor
516kW/4p/380V, Xxx47.2Mx, Xxx61x4F, Xxx61x4G, Xxx61x4H or Xxx61x4J	Polyphase Motor
364kW/4p/208V, Xxx47.2Sx or Xxx61x4D	Polyphase Motor
440kW/4p/220V, Xxx47.2Sx or Xxx61x4D	Polyphase Motor
456kW/4p/240V, Xxx47.2Sx or Xxx61x4D	Polyphase Motor
456kW/4p/380V, Xxx47.2Sx or Xxx61x4D	Polyphase Motor
436kW/4p/208V, Xxx47.2Sx or Xxx61x4D	Polyphase Motor
364kW/4p/200V, Xxx47.2Sx or Xxx61x4D	Polyphase Motor
352kW/4p/440V, Xxx47.2Sx or Xxx61x4D	Polyphase Motor

B. Mahlen

Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number UL-CA-L252760-32-41301102-2
 Report Reference E252760-20110314
 Date 4-Dec-2021

456kW/4p/300V, Xxx47.2Sx or Xxx61x4D	Polyphase Motor
392kW/4p/190V, Xxx47.2Sx or Xxx61x4D	Polyphase Motor
320kW/4p/200V, Xxx47.2VSx or Xxx61x4B	Polyphase Motor
372.8kW/4p/220V, Xxx47.2VSx or Xxx61x4B	Polyphase Motor
396kW/4p/240V, Xxx47.2VSx or Xxx61x4B	Polyphase Motor
396kW/4p/208V, Xxx47.2VSx or Xxx61x4B	Polyphase Motor
396kW/4p/190V, Xxx47.2VSx or Xxx61x4B	Polyphase Motor
384kW/4p/300V, Xxx47.2VSx or Xxx61x4B	Polyphase Motor
Xxx47.2VSx, Xxx61x4B, Xxx61x4C, KH01630Txxx, KH01741Txxx - 3ph)	Polyphase Motor
Xxx47.3Lx - (3ph)	Polyphase Motor
Xxx47.3Mx - (3ph)	Polyphase Motor
Xxx47.3Sx - (3ph)	Polyphase Motor
Xxx47.3VSx - (3ph)	Polyphase Motor
728kW/4p/200V, Xxx49.1Lx, Xxx70x4P, Xxx71x4P, 12x8 or xx44xLxxxx	Polyphase Motor
840kW/4p/220V, Xxx49.1Lx, Xxx70x4P, Xxx71x4P, 12x8 or xx44xLxxxx	Polyphase Motor
824kW/4p/190V, Xxx49.1Lx, Xxx70x4P, Xxx71x4P, 12x8 or xx44xLxxxx	Polyphase Motor
824kW/4p/208V, Xxx49.1Lx, Xxx70x4P, Xxx71x4P, 12x8 or xx44xLxxxx	Polyphase Motor
912kW/4p/300V, Xxx49.1Lx, Xxx70x4P, Xxx71x4P, 12x8 or xx44xLxxxx	Polyphase Motor
1000kW/4p/480V, Xxx49.1Lx, Xxx70x4P, Xxx71x4P, 12x8 or xx44xLxxxx	Polyphase Motor
800kW/4p/380V, Xxx49.1Lx, Xxx70x4P, Xxx71x4P, 12x8 or xx44xLxxxx	Polyphase Motor
865kW/4p/416V, Xxx49.1Lx, Xxx70x4P, Xxx71x4P, 12x8 or xx44xLxxxx	Polyphase Motor
920kW/4p/440V, Xxx49.1Lx, Xxx70x4P, Xxx71x4P, 12x8 or xx44xLxxxx	Polyphase Motor
800kW/4p/400V, Xxx49.1Lx, Xxx70x4P, Xxx71x4P, 12x8 or xx44xLxxxx	Polyphase Motor
712kW/4p/190V, Xxx49.1Lx, Xxx70x4P, Xxx71x4P, 12x8 or xx44xLxxxx	Polyphase Motor
874kW/4p/240V, Xxx49.1Lx, Xxx70x4P, Xxx71x4P, 12x8 or xx44xLxxxx	Polyphase Motor
640kW/4p/200V, Xxx49.1Mx, Xxx70x4L, Xxx70x4J, 12x6 or xx44xMxxxx	Polyphase Motor
784kW/4p/300V, Xxx49.1Mx, Xxx70x4L, Xxx70x4J, 12x6 or xx44xMxxxx	Polyphase Motor
784kW/4p/240V, Xxx49.1Mx, Xxx70x4L, Xxx70x4J, 12x6 or xx44xMxxxx	Polyphase Motor
784kW/4p/208V, Xxx49.1Mx, Xxx70x4L, Xxx70x4J, 12x6 or xx44xMxxxx	Polyphase Motor

B. Mahlen

Bruce Mahlenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number UL-CA-L252760-32-41301102-2
 Report Reference E252760-20110314
 Date 4-Dec-2021

784kW/4p/220V, Xxx49.1Mx, Xxx70x4L, Xxx70x4J, 12x6 or xx44xMxxxx	Polyphase Motor
784kW/4p/190V, Xxx49.1Mx, Xxx70x4L, Xxx70x4J, 12x6 or xx44xMxxxx	Polyphase Motor
528kW/4p/200V, Xxx49.1Sx, Xxx70x4D, Xxx70x4F or Xxx70x4H	Polyphase Motor
656kW/4p/300V, Xxx49.1Sx, Xxx70x4D, Xxx70x4F or Xxx70x4H	Polyphase Motor
656kW/4p/240V, Xxx49.1Sx, Xxx70x4D, Xxx70x4F or Xxx70x4H	Polyphase Motor
656kW/4p/190V, Xxx49.1Sx, Xxx70x4D, Xxx70x4F or Xxx70x4H	Polyphase Motor
656kW/4p/208V, Xxx49.1Sx, Xxx70x4D, Xxx70x4F or Xxx70x4H	Polyphase Motor
656kW/4p/220V, Xxx49.1Sx, Xxx70x4D, Xxx70x4F or Xxx70x4H	Polyphase Motor
Xxx49.3Lx, Xxx72x4N, Xxx72x4P, KH00390Txxx, KH03542Txxx - (3ph)	Polyphase Motor
Xxx49.3Mx, Xxx72x4J, Xxx72x4L, KH02850Txxx, KH03003Txxx - (3ph)	Polyphase Motor
Xxx49.3Sx, Xxx72x4H, KH02401Txxx - (3ph)	Polyphase Motor
xxx4P3.x-0001 to 1260	Polyphase Motor
xxx4P3.x-1261 to 2050	Polyphase Motor
1500kW/4p/208V, xxx4P5.x-xxxx	Polyphase Motor
xxx4P8.x-3450	Polyphase Motor
xxx4P9.x-0001 to 1800 CACA	Polyphase Motor
xxx4P9.x-0001 to 1800, xx94xSxxxx, xx94xLxxxx, 30xx, or 31xx	Polyphase Motor
xxx4P9.x-1801 to 2100 CACA	Polyphase Motor
xxx4P9.x-1801 to 2100, xx94xSxxxx, xx94xLxxxx, 30xx, or 31xx	Polyphase Motor
xxx4P9.x-2101 to 2250, xx94xMxxxx, xx94xVLxxxx, 30xx, or 31xx	Polyphase Motor
xxx4P9.x-2101 to 2400 CACA	Polyphase Motor
xxx4P9.x-2251 to 2400, xx94xMxxxx, xx94xVLxxxx, 30xx, or 31xx	Polyphase Motor
xxx4P9.x-2401 to 2700 CACA	Polyphase Motor
xxx4P9.x-2401 to 2700, xx94xMxxxx, xx94xVLxxxx, 30xx, or 31xx	Polyphase Motor
xxx4P9.x-2701 to 2950 CACA	Polyphase Motor
xxx4P9.x-2701 to 2950, xx94xLxxxx, 30xx, or 31xx	Polyphase Motor
xxx4P9.x-2951 to 3200 CACA	Polyphase Motor
xxx4P9.x-2951 to 3200, xx94xLxxxx, 30xx, or 31xx	Polyphase Motor
1500kW/4p/208V, Xxx50.2Lx	Polyphase Motor
1500kW/4p/240V, Xxx50.2Lx, Xxx82x4L, Xxx82x4N, 144x-xxx, xxx4P5.x-xxxx, xxx54xLxx	Polyphase Motor

B. Mahlen

Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number UL-CA-L252760-32-41301102-2
Report Reference E252760-20110314
Date 4-Dec-2021

1500kW/4p/300V, Xxx50.2Lx, Xxx82x4L, Xxx82x4N, 144x-xxx, xxx4P5.x-xxxx, xxx54xLxx	Polyphase Motor
1500kW/4p/220V, Xxx50.2Lx, Xxx82x4L, Xxx82x4N, 144x-xxx, xxx4P5.x-xxxx, xxx54xLxx	Polyphase Motor
1200kW/4p/200V, Xxx50.2Lx, Xxx82x4L, Xxx82x4N, 144x-xxx, xxx4P5.x-xxxx, xxx54xLxx	Polyphase Motor
1376kW/4p/190V, Xxx50.2Lx, Xxx82x4L, Xxx82x4N, 144x-xxx, xxx4P5.x-xxxx, xxx54xLxx	Polyphase Motor
1272kW/4p/300V, Xxx50.2Mx, Xxx82x4H, 142x-xxx, xxx4P5.x-xxxx or xxx54xMxx	Polyphase Motor
1240kW/4p/220V, Xxx50.2Mx, Xxx82x4H, 142x-xxx, xxx4P5.x-xxxx or xxx54xMxx	Polyphase Motor
1240kW/4p/208V, Xxx50.2Mx, Xxx82x4H, 142x-xxx, xxx4P5.x-xxxx or xxx54xMxx	Polyphase Motor
1272kW/4p/240V, Xxx50.2Mx, Xxx82x4H, 142x-xxx, xxx4P5.x-xxxx or xxx54xMxx	Polyphase Motor
1060kW/4p/200V, Xxx50.2Mx, Xxx82x4H, 142x-xxx, xxx4P5.x-xxxx or xxx54xMxx	Polyphase Motor
1200kW/4p/190V, Xxx50.2Mx, Xxx82x4H, 142x-xxx, xxx4P5.x-xxxx or xxx54xMxx	Polyphase Motor
1040kW/4p/300V, Xxx50.2Sx, Xxx82x4A, Xxx82x4B, 140x-xxx, xxx4P5.x-xxxx, xxx54xSxxx	Polyphase Motor
1040kW/4p/220V, Xxx50.2Sx, Xxx82x4A, Xxx82x4B, 140x-xxx, xxx4P5.x-xxxx, xxx54xSxxx	Polyphase Motor
1040kW/4p/208V, Xxx50.2Sx, Xxx82x4A, Xxx82x4B, 140x-xxx, xxx4P5.x-xxxx, xxx54xSxxx	Polyphase Motor
1040kW/4p/240V, Xxx50.2Sx, Xxx82x4A, Xxx82x4B, 140x-xxx, xxx4P5.x-xxxx, xxx54xSxxx	Polyphase Motor
832kW/4p/200V, Xxx50.2Sx, Xxx82x4A, Xxx82x4B, 140x-xxx, xxx4P5.x-xxxx, xxx54xSxxx	Polyphase Motor
992kW/4p/190V, Xxx50.2Sx, Xxx82x4A, Xxx82x4B, 140x-xxx, xxx4P5.x-xxxx, xxx54xSxxx	Polyphase Motor
1600kW/4p/240V, Xxx50.2VLxx, Xxx82x4P, 146x-xxx, 148x-xxx, xxx4P5.x-xxxx or xxx54xVLxx	Polyphase Motor
1600kW/4p/300V, Xxx50.2VLxx, Xxx82x4P, 146x-xxx, 148x-xxx, xxx4P5.x-xxxx or xxx54xVLxx	Polyphase Motor
1600kW/4p/208V, Xxx50.2VLxx, Xxx82x4P, 146x-xxx, 148x-xxx, xxx4P5.x-xxxx or xxx54xVLxx	Polyphase Motor
1600kW/4p/220V, Xxx50.2VLxx, Xxx82x4P, 146x-xxx, 148x-xxx, xxx4P5.x-xxxx or xxx54xVLxx	Polyphase Motor
1312kW/4p/200V, Xxx50.2VLxx, Xxx82x4P, 146x-xxx, 148x-xxx, xxx4P5.x-xxxx or xxx54xVLxx	Polyphase Motor
1476kW/4p/190V, Xxx50.2VLxx, Xxx82x4P, 146x-xxx, 148x-xxx, xxx4P5.x-xxxx or xxx54xVLxx	Polyphase Motor
1600kW/4p/240V, Xxx50.xXLx, 148x-xxx, xxx4P5.x-xxxx or xxx54xXLxx	Polyphase Motor

B. Mahlen

Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number UL-CA-L252760-32-41301102-2
Report Reference E252760-20110314
Date 4-Dec-2021

1600kW/4p/300V, Xxx50.xXLx, 148x-xxx, xxx4P5.x-xxxx or xxx54xXLxx	Polyphase Motor
1600kW/4p/208V, Xxx50.xXLx, 148x-xxx, xxx4P5.x-xxxx or xxx54xXLxx	Polyphase Motor
1600kW/4p/220V, Xxx50.xXLx, 148x-xxx, xxx4P5.x-xxxx or xxx54xXLxx	Polyphase Motor
1312kW/4p/200V, Xxx50.xXLx, 148x-xxx, xxx4P5.x-xxxx or xxx54xXLxx	Polyphase Motor
1476kW/4p/190V, Xxx50.xXLx, 148x-xxx, xxx4P5.x-xxxx or xxx54xXLxx	Polyphase Motor
1728kW/4p/200V, Xxx51.xLxx, Xxx9xx4L, 164x-xxx, xxx4P6.x-xxxx or xxx64xLxx	Polyphase Motor
2150.4kW/4p/240V, Xxx51.xLxx, Xxx9xx4L, 164x-xxx, xxx4P6.x-xxxx or xxx64xLxx	Polyphase Motor
2150.4kW/4p/300V, Xxx51.xLxx, Xxx9xx4L, 164x-xxx, xxx4P6.x-xxxx or xxx64xLxx	Polyphase Motor
2065kW/4p/208V, Xxx51.xLxx, Xxx9xx4L, 164x-xxx, xxx4P6.x-xxxx or xxx64xLxx	Polyphase Motor
2065kW/4p/190V, Xxx51.xLxx, Xxx9xx4L, 164x-xxx, xxx4P6.x-xxxx or xxx64xLxx	Polyphase Motor
2065kW/4p/220V, Xxx51.xLxx, Xxx9xx4L, 164x-xxx, xxx4P6.x-xxxx or xxx64xLxx	Polyphase Motor
1920kW/4p/220V, Xxx51.xMxx, Xxx9xx4H, 162x-xxx, Xxx4P6.x-xxxx or Xxx64xMxx	Polyphase Motor
2000kW/4p/240V, Xxx51.xMxx, Xxx9xx4H, 162x-xxx, Xxx4P6.x-xxxx or Xxx64xMxx	Polyphase Motor
1885kW/4p/190V, Xxx51.xMxx, Xxx9xx4H, 162x-xxx, Xxx4P6.x-xxxx or Xxx64xMxx	Polyphase Motor
1920kW/4p/208V, Xxx51.xMxx, Xxx9xx4H, 162x-xxx, Xxx4P6.x-xxxx or Xxx64xMxx	Polyphase Motor
1640kW/4p/200V, Xxx51.xMxx, Xxx9xx4H, 162x-xxx, Xxx4P6.x-xxxx or Xxx64xMxx	Polyphase Motor
2000kW/4p/300V, Xxx51.xMxx, Xxx9xx4H, 162x-xxx, Xxx4P6.x-xxxx or Xxx64xMxx	Polyphase Motor
1800kW/4p/240V, Xxx51.xSxx, Xxx9xx4F, 160x-xxx, xxx4P6.x-xxxx or xxx64xSxx	Polyphase Motor
1800kW/4p/300V, Xxx51.xSxx, Xxx9xx4F, 160x-xxx, xxx4P6.x-xxxx or xxx64xSxx	Polyphase Motor
1728kW/4p/208V, Xxx51.xSxx, Xxx9xx4F, 160x-xxx, xxx4P6.x-xxxx or xxx64xSxx	Polyphase Motor
1650kW/4p/190V, Xxx51.xSxx, Xxx9xx4F, 160x-xxx, xxx4P6.x-xxxx or xxx64xSxx	Polyphase Motor
1728kW/4p/220V, Xxx51.xSxx, Xxx9xx4F, 160x-xxx, xxx4P6.x-xxxx or xxx64xSxx	Polyphase Motor
1488kW/4p/200V, Xxx51.xSxx, Xxx9xx4F, 160x-xxx, xxx4P6.x-xxxx or xxx64xSxx	Polyphase Motor

B. Mahlen

Bruce Mahlenholz, Director North American Certification Program

UL LLC


Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number UL-CA-L252760-32-41301102-2
Report Reference E252760-20110314
Date 4-Dec-2021

1800kW/4p/200V , Xxx51.xVLxx, Xxx9xx4P, 166x-xxx, xxx4P6.x-xxxx or xxx64xVLxx	Polyphase Motor
2250.4kW/4p/240V , Xxx51.xVLxx, Xxx9xx4P, 166x-xxx, xxx4P6.x-xxxx or xxx64xVLxx	Polyphase Motor
2250.4kW/4p/300V , Xxx51.xVLxx, Xxx9xx4P, 166x-xxx, xxx4P6.x-xxxx or xxx64xVLxx	Polyphase Motor
1952kW/4p/208V , Xxx51.xVLxx, Xxx9xx4P, 166x-xxx, xxx4P6.x-xxxx or xxx64xVLxx	Polyphase Motor
1800kW/4p/190V , Xxx51.xVLxx, Xxx9xx4P, 166x-xxx, xxx4P6.x-xxxx or xxx64xVLxx	Polyphase Motor
2068kW/4p/220V , Xxx51.xVLxx, Xxx9xx4P, 166x-xxx, xxx4P6.x-xxxx or xxx64xVLxx	Polyphase Motor
52 , xxx52.xLxx, xxx9xx4x, xx4P6.x-xxxx, or xxx64xLxx	Polyphase Motor
52 , xxx52.xSxx, xxx9xx4x, xx4P6.x-xxxx, or xxx64xSxx	Polyphase Motor
1500kW/4p/208V , xxx54xLxx	Polyphase Motor
1500kW/4p/208V , Xxx82x4L	Polyphase Motor
1500kW/4p/208V , Xxx82x4N	Polyphase Motor
xxx84xULxx	Polyphase Motor



Bruce Mahrenholz, Director North American Certification Program

UL LLC



Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>